








 A	 B
1 PC	1 SET
 C	 D
1 PC	2 PCS
 E	 F
M3,5*16mm 2 PCS	M3,5*12mm 1 PC

PASO 1




Diagram illustrating the first step of assembly: attaching the side panel (A) to the cabinet frame. The diagram shows the side panel being aligned with the top and bottom rails. Callouts indicate the placement of screws: C (top rail), D*2 (top rail), and E*2 (bottom rail).

PASO 2




Diagram illustrating the second step of assembly: attaching the top panel (F) to the cabinet frame. The diagram shows the top panel being aligned with the side panels. Callouts indicate the placement of screws: B (top panel) and F (top panel).

PASO 3




Diagram illustrating the third step of assembly: final assembly. The diagram shows the completed cabinet with all panels attached and screws tightened.